

# REPORT

## TRUESDAIL LABORATORIES, INC.



CHEMISTS - MICROBIOLOGISTS - ENGINEERS  
RESEARCH - DEVELOPMENT - TESTING  
ESTABLISHED 1931

14201 FRANKLIN AVENUE  
TUSTIN, CALIF. 92680  
(714) 730-6239 • (213) 225-1564  
FAX (714) 730-6462

CLIENT: Douglas Aircraft Company  
Internal Mail Code 74-41  
3855 Lakewood Blvd.  
Long Beach, CA 90846  
ATTN: Boramy Ith

REPORT DATE: March 16, 1993

RECEIVED: Feb 18, 1993

LABORATORY NUMBER: 58136 ✓

Water from Stormdrain, Torrance Facility  
P.O. Number: T & M 25998-C

First Quarter, 1993, Analysis as Required by NPDES Permit #CA0001414

### RESULTS

Flow, Total(GPD)	4,754
Temperature, °F	60
pH, Units (EPA 150.1)	7.8

### MILLIGRAMS PER LITER

Parameter	Method	Detection Limit	Concentration
Biochemical Oxygen Demand	405.1	2.0	8.1
Chromium	200.7	0.01	ND
Oil and Grease	413.1	6.0	13.9
Settleable Solids (ml/L/hr)	160.5	0.20	ND
Total Suspended Solids	160.2	4.0	ND

\*ND = Not detected, below detection limit

Respectfully Submitted,  
Truesdail Laboratories, Inc.

Thomas Herrin, Manager  
Environmental Field Services

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.